



TRIDENT SOLUTIONS™

Innovation - Protection - Identification

# Rhino HIT Kit +2™ Fact Sheet

For larger damage investigation areas.  
Part# HK220



The Rhino HIT Kit +2™ is used to enhance root cause investigations and to accurately record damage to buried facilities such as fiber optic cable, pipelines, electrical lines, and more. Use of the HIT Kit +2™ allows for consistent photographing of a large area for damage reporting by using a standard tool to record every accident which can reduce unnecessary and costly legal actions when damage occurs. It also assists in identifying locate marks for a clearer depiction of the scene.

### Description:

- Made with RhinoPoly® – our proprietary blend of thermoplastics
- 3 “MARK” posts with 3, 2-7/8" x 14" bold legends
- 1 “DAMAGE” post with 3, 2-7/8" x 14" bold legends
- 36", 48" or 72" rigid ruler with a guide on the back
- 4 marker post bases
- 8 spikes for holding posts in place
- Durable carrying bag
- French and Spanish decals available
- Metric ruler available



HIT Kit Tutorial Video



Order Online

## Options & Add-Ons



Additional “DAMAGE” Post with Stand & Spike  
Part# HK-DMG-Y



Additional “MARK” Post with Stand & Spike  
Part# HK-MARK-0



Replacement Stands  
Part# HK-STAND-KIT



Dry Erase Board Kit  
Part# HK-DE-KIT



Replacement Bag  
Part# HK-BAG-XL